

CERTIFICATION by CUSTODIAN of RECORDS Tucson Police Department Crime Laboratory



I hereby certify that these documents are a true and correct copy of the

periodic maintenance* for the Intoxilyzer 8000 Serial Number 80-000334 ____ maintained by the Tucson Police Department Crime Laboratory pursuant to the requirements of the Arizona Department of Public Safety for a quality assurance program. A quality assurance specialist (QAS) tested the instrument on the following dates. The acceptable accuracy limits, as defined in A.A.C. R13-10-104.A.2, for a 0.100AC solution are 0.090AC to 0.110AC. Date: 6-21-2007 Cal 1 0.098 AC Cal 2 0.098 Between the dates of 5.24.2007 and 6.21.2007 the instrument was operating properly and accurately. The instrument was taken out of service for repair on _____ The instrument was returned to service on — Terry S. Gallegos 7,13.2007 ADPS QAS Permit # 33169 SUBSCRIBED AND SWORN to before me this____ OFFICIAL SEAL KATHY A. KINNEY NOTARY PUBLIC-ARIZONA

*Includes documents specified in A.A.C. R13-10-104.A.5

/ PIMA COUNTY
My Comm. Exp. Sept. 4, 2008

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

Notary Public

EXHIBIT G-4

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

STANDARD QUALITY ASSURANCE PROCEDURE

QA SPECIALIST Terry Galley 3847 AGENCY Tucson Police Department
QA SPECIALIST 10VY Galley 3847 AGENCY Tucson Police Department DATE 6-21-2007 TIME 1842
INTOXILYZER SERIAL # 80-000334 LOCATION DUT HQ
() 1. Display reads "PUSH BUTTON TO START"
DIAGNOSTIC TESTS
1. Clock time check. 2. Date check.
OPERATIONAL TESTS
1. Alcohol-free subject test result 0. <u>DOO</u> AC. 2. Error recognition logic system functioning. Not a Successfully Completed Test Sequence printed 3. Proper sample recognition system. Not a Successfully Completed Test Sequence printed Deficient sample printed. 4. Standard Calibration Check standard 0. <u>DOO</u> AC Result: 0. <u>D48</u> AC
Instrument is operating properly and accurately. YESNO
COMMENTS
SIGNATURE Sely Gally

DPS Form Exh G-4 (Rev. 05-01)

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

10f 7 154 mgs

Location: TUCSON POLICE DEPT

Serial Number: 80-000334

06/21/2007

18:44:06

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS

#28847

QAS: T. GALLEGOS

#28847

TUCSON PD CRIME LAB

Operator: T. GALLEGOS

TUCSON PD CRIME LAB

#28847

Subject: SQAP, SQAP

DOB: 11/11/1111

Sex: F

Weight: 111

15 Minute Deprivation Period? Yes

		•
Test	g/210L	Time
Air Blank "	0.000	18:45:09
Diagnostic Test	Pass	18:45:37
Air Blank	0.000	18:46:04
0.100 Cal Check	0.098	18:46:23
Air Blank	0.000	18:46:53
Subject Test	0.000 .	18:47:11
Air Blank	0.000	18:47:38
Five Minute Wait	ABT*	
Air Blank	0.000	18:48:16

^{*}Sequence Aborted

Location: TUCSON POLICE DEPT

Serial Number: 80-000334

06/21/2007

18:48:21

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS

#28847

QAS: T. GALLEGOS

#28847

TUCSON PD CRIME LAB

Operator: T. GALLEGOS

#28847

TUCSON PD CRIME LAB

Subject: SQAP, SQAP

DOB: 11/11/1111

Sex: F

Weight: 111

15 Minute Deprivation Period? Yes

		•
Test	g/210L	Time
Air Blank	0.000	18:49:11
Diagnostic Test	Pass	18:49:38
Air Blank	RFI*	18:49:56
Air Blank	IPS**	18:50:10

^{*}RFI Detect

^{**}Improper Sample

Location: TUCSON POLICE DEPT

Serial Number: 80-000334

06/21/2007

18:50:44

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS

#28847

QAS: T. GALLEGOS

#28847

TUCSON PD CRIME LAB

Operator: T. GALLEGOS

#28847

TUCSON PD CRIME LAB

Subject: SQAP, SQAP DOB: 11/11/1111

Sex: F

Weight: 111

15 Minute Deprivation Period? Yes

		•
Test	g/210L	Time
Air Blank	0.000	18:51:39
Diagnostic Test	Pass	18:52:07
Air Blank	0.000	18:52:34
0.100 Cal Check	0.099	18:52:53
Air Blank	0.000	18:53:23
Subject Test	0.142*.	18:56:31
Air Blank	0.000	18:57:04
Air Blank	0.000	18:57:32
Subject Test	XXX**	18:57:49
Air Blank	0.000	18:58:23

^{*}Deficient Sample

Begin new deprivation period

Not a Successfully Completed Test Sequence
Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

40+7 TSh 7000

^{**}Invalid Sample

Location: TUCSON POLICE DEPT

Serial Number: 80-000334

06/21/2007

18:59:03

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS #28847

QAS: T. GALLEGOS #28847 TUCSON PD CRIME LAB

Test	g/210L	Time
Air Blank	0.000	18:59:31
Cal Check	0.098	18:59:49
Air Blank	0.000	19:00:20

Operator's Signature

EXHIBIT G-2

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R13-10-104(A)

ARIZONA DEPARTMENT OF PUBLIC SAFETY

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 8000

STANDARD CALIBRATION CHECK PROCEDURE

QA Spe	eciali	t Terry Gallego'S 28947 AGENCY Tucson Police Department 1. 2007 TIME 1842
DATE	6-2	1. 2007 TIME 1842
Intox	ilyzer	Serial # 80-000334 Location DUI HO
	1.	Ensure that gas tank is attached to instrument and contains a standard alcohol concentration solution 0.100 AC.
		Pour a standard alcohol concentration solutionAC, into a clean dry simulator and assemble the simulator. Ensure that a tight seal has been made. Turn on the simulator and allow temperature to reach 34°C \pm 0.2°C
		Intoxilyzer 8000 display reads "PUSH BUTTON TO START"
()	3.	Go to the "Control Testing Menu". Select "D" for dry control test or "W" for wet control test. After selection is made press ENTER.
()	4.	Air blank completed.
(🗸)		Calibration check completed. Test results 0. 09
()		Air blank completed.
(1	7.	Remove printed record. Attach the record to the completed checklist.
SIGNA	TURE	Leny Gally

DPS Form Exh G-2 (Rev. 05-01)

Location: TUCSON POLICE DEPT

Serial Number: 80-000334

06/21/2007 18:42:42

Standard Lot#: 627101G

Last Changed By: T. GALLEGOS #28847

QAS: T. GALLEGOS #28847 TUCSON PD CRIME LAB

 tof 7